

The Scott Estate

Milan, OH

OWNER: Mr. Rod Scott

LOCATION: North End East Side (above porch)

EQUIPMENT: Vinyl Siding

FINDINGS: Suspect Thermal Loss due to lack of insulation and/or excessive air flow.

RECOMMENDATION: Further inspect the area of loss and repair as required.

EXCEPTION TEMP. (Area 1): 37F

REFERENCE (Normal) (Area 2): 12F


DELTA-T: 25F

PRIORITY RATING: (NETA STANDARDS)

Indicates major discrepancy; repair immediately.

PRIORITY 3

Further inspections should be completed by a professional builder or at the home owners own risk!



Thermal Infrared Exception Image



Visual Control Photo

Notes of repairs following the inspection: