

# Company Name

City, State

# Priority

# 1

## INVENTORY No. 027

**COMPANY TECHNICIAN:** Mr. Rod Scott

**ADDRESS:** 2519 State Route 61  
Norwalk Plant

**LOCATION:** Pump House No.3

**EQUIPMENT:** Plant No.1 Main Pump

Line No.1

**FINDINGS:** Uneven thermal pattern on coupling & End-Bell temperatures exceed maximum rise.

**RECOMMENDATIONS:** Inspect load, shaft alignment and lubrication and comply with manufacturers specification.

**EXCEPTION TEMP. (pt.1):** 188F


**REFERENCE TEMP. (pt.2):** 170F

**DELTA-T:** 18F


**PRIORITY RATING: (NETA STANDARDS)**

*Possible deficiency and warrants investigation.*

**PRIORITY 1**



**Visual Control Photo**



**Thermal Infrared Image**

**Notes:**